

# Volvo EC460 CL Machine History

MAKE & MODEL	SERIAL NUMBER	FLEET NUMBER
VOLVO EC460 CL	110221	1130

<b>PURCHASE DATE</b>	15/05/08
<b>WALTHAM ABBEY SITE =</b>	HYD OIL – BIO HYDRAN TMP 46
<b>Radio code:</b>	VDCD47620031635
<b>Start Up Code:</b>	4819
<b><u>GEITH QUICK HITCH -</u></b>	
<b>PRODUCT -</b>	QH110H-AL
<b>SERIAL NUMBER-</b>	Z83170
<b>MACHINE TYPE-</b>	VOLVO EC460C
<b>CAPACITY-</b>	LIFT EYE
<b>HYD FLOW RATE -</b>	5.8 GAL/MIN 26.6 LT/MIN
<b>HYD WORKING PRESSURE-</b>	350 BAR 5000.0 PSI
<b>YEAR OF MAN -</b>	2009
<b>DATE OF PURCHASE -</b>	DEC 09

DATE	HOURS	ACTION COMPLETED	W/S NUMBER
22/07/08		CHECK HYD OVERHEATING. CHECK HYD TANK OIL LEVEL OK. CHECK HYD OIL COOLER. BLACK PLASTIC BAG COVERING 2/3 OFF HYD COOLER BEHIND AIR CON COOLER. CLEAN OUT DRIVER TITAVATING KIT FROM IN FRONT OF COOLER.	EAMON – 22903
23/07/08		VOLVO ENGINEER ON SITETO CHECK IF ANY FAULT CODES. NO FAULT CODES FOUND. ENGINE CHECK NO FAULTS FOUND.	EAMON - 22903
12/08/08	285	<b>250 HRS SERVICE:</b> CHANGE FUEL FILTERS. CHECK LEVELS. CHECK LIGHTS. (FINAL DRIVE LEVELS LOW. HYD OIL LEVELS LOW. )	STEVE P - 21211
03/11/08	571	<b>500 HRS SERVICE:</b> CHANGE ENGINE OIL AND FILTERS. CHANGE FUEL FILTERS. CHECK LEVELS AND LIGHTS. CHECK ANTIFREEZE.	STEVE P - 23186
08/01/09	859	<b>750 HRS SERVICE:</b> CHANGE FUEL FILTERS. CHECK LEVELS. AND LIGHTS. CHECK ANTIFREEZE. (HEAD LIGHT SWITCH U/S)	STEVE P - 23508
25/02/09	1064	<b>1000 HRS SERVICE:</b> CHANGE ENGINE OIL AND FILTER. CHANGE FUEL FILTER. CHANGE HYD FILTER. CHANGE HYD SUCTION FILTER. CHANGE HYD BREATHER CAP FILTER. CHANGE FINAL DRIVE OILS. CHANGE SWING BOX OILS. CHANGE AIR FILTER. CHANGE CAB FILTERS. CHANGE AIR CON FILTER.	STEVE P - 23959
04/03/09		ATLAS COPCO 4200 HAMMER 1094. ADJUST AUTO GREASE TO CUT DOWN GREASE TO 1 ½ TUBES FROM 3.	EAMON - 24323
04/04/09	1315	<b>250 HRS SERVICE:</b> CHANGE FUEL FILTER. CHECK LIGHTS AND LEVELS. CHECK BELTS.	STEVE P - 24671
27/06/09	1558	<b>500 HRS SERVICE –</b> CHANGE ENGINE OIL AND FILTER. CHANGE FUEL FILTER. CHECK LIGHTS AND LEVELS. CHECK BELTS. CHECK ANTIFREEZE. GREASE BUCKET PINS. BLOW AIR FILTERS. (ROOF LIGHT SWITCHG US NEEDS REPLACEING)	STEVE P - 25828
20/07/09	1649	REPLACE HAMMER SEWEVEL SEALS. FIT 2 GREASE PIPE ENDS. TOP UP HYD OIL.,	STEVE L - 25403
19/09/09	1826	<b>750 HRS SERVICE –</b> REBOLT HAMMER TO MACHINE. FIT 1 HOSE. CHNAGED FUEL FILTERS AND CHECK MACHINE OIL LEVELS.	STEVE L - 25449

# Volvo EC460 CL Machine History

28/11/09	2069	<b>1000 HRS SERVICE</b> – CHANGE ENGINE OIL AND FILTERS. CHANGE FUEL FILTERS. CHANGE HYD FILTERS TANK ND INLINE. CHANGE AIR FILTERS. CHANGE AIR CON FILTER CHANGE CAB FILTER. CHANGE SWING BOX OILS. CHANGE FINAL DRIVE OILS. CHECK BELT. CHECK LIGHTS AND LEVELS. AND ANTIFREEZE. ORANGE LIGHT NOT SPRINNING U/S. BAYONETT TYPE.	STEVE P - 26259
27/02/10	2475	<b>250 HRS SERVICE</b> – CHANGE FUEL FILTERS. CHECK OIL LEVELS. CLEAN AIR FILTERS. CHECK MACHINE	PAUL R - 26594
23/03/10	2604	REMOVE LEAKING HOSE BLANK OFF FIT TEMP HOSE AND ORDER CORRECT ONE.	STEVE L - 270151005
27/03/10		FIT NEW HOSE	STEVE L - 27015
07/04/10	2640	FIT YELLOW FLASHING BEACON	PAUL L - 27104
06/05/10	2822	<b>500 HRS SERVICE</b> – CHANGED ENGINE OIL CHANGED. FILTERS CHANGED ENG AND FUEL. AIR FILTERS BLOWN OUT. HYD OIL TOPPED UP COOLANT TOPPED UP. ALL LIGHTS CHECKED. SAMPLES TAKEN ENG AND HYD	MARK L - 27238
10/05/10	2823	FIT NEW BOLT IN BUCKET PIN BUCKET NO 513 REPAIR GREASE PIOES ON QUICK RELEASE	PAUL L - 27501
09/06/10	3006	WELD BOXING RING PILLERS BACK ON HOLDING DOWN PLATE	PAUL L - 27537
15/06/10	3031	WELD PLATE ON QUICK HITCH	PAUL L - 27543
17/07/10	3181	<b>750 HRS SERVICE</b> – FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. ALL OIL LEVELS CHECKED. COOLANT CHECKED. ALL LIGHTS CHECKED.	MARK L - 28014
10/08/10	3322	REPLACED BOLTS IN BUCKET PINS	STEVE L - 27649
11/09/10	3488	<b>1000 HRS SERVICE</b> – OIL CHANGED. ENG AND FINAL DRIVES. FILTERS CHANGED ENG FUEL HYD AIR AND CAB. ALL OIL LEVELS OK. COOLANT OK. AND LIGHTS, MACHINE GRESED. SAMPLES TAKEN ENG HYD SLEW FINAL DRIVES	MARK L - 28248
30/09/10	3590	STRAIGHTEN TRACK STEPS	STEVE L - 28510
28/10/10	3749	ANTI FREEZE -32. OIL LEVELS CHECKED ENG AND HYD TOPPED UP. COOLANT TOPPED UP. AIR FILTERS BLOWN OUT. LIGHTS	MARK L - 28597
05/11/10	3775	<b>250 HRS SERVICE</b> – CHNAGED FUEL FILTERS. ENG OIL OK. HYD OIL OK SLEW OIL OK. TRACK DRIVE MOTORS OK. LIGHTS OK HORN OK	PAUL L - 28761
05/01/11	4017	REPAIR BOXING RING TAKE OF SUPORTS REWLED BRAKETS	PAUL L - 29006
12/01/11	4055	<b>500 HRS SERVICE</b> –	PAUL L - 29017
25/1/11	4128	REWELD BOXING RING. COULD NOT REPLACE UP RIGHTS AS OLD ONES HAVE BEEN WELDED IN PLACE NEEDS 6 NEW UP RIGHTS AND CHAINS IN BETWEEN UP RIGHTS	PAUL L - 29028
31/3/11		HYD HOSE 66’’ LONG LIFTING CERT OUT OF DATE	PAUL L - 29483
16/5/11	4691	<b>1000 HRS SERVICE</b> – ENG OIL SLEW AND FINAL DRIVES CHANGED. FILTERS CHNAGED ENG FUEL AIR HYD CAB AND BREATHERS. OIL LEVELS CHECKED HYD TOPPED UP. COOLANT TOPPED UP. ANTIFREEZE – 32 BATTERY S CHECKED CLEANED AND GREASED. MACHINE GREASED. LIGHST OK. SAMPLES TAKEN ENG HYD SLEW AND FINAL DRIVES WIDNSCREEN CRACKED TOP AND BOTTOM	MARK L - 30258
02/6/11	4804	REPLACED DOUTY SEAL ON QUICK RELASE RAM. RETIGHTEN HAND RAIL ON BOXING RING	PAUL L - 30032
04/7/11	5012	<b>250 HRS SERVICE</b> – CHNAGED FUEL FILTERS. WELD CRACK IN BUCKET MAIN SKIN THIN.	PAUL L - 30814
22/7/11	5090	ENG OIL CHNAGED. OIL LEVELS CHECKED COOLANT CHECKED. AIR FILTERS BLOWN OUT. LIGHTS CHECKED	MARK L - 30947
03/8/11		<b>VOLVO</b> – INTERMITTANT AC FAULT INVESTIGATE SYSTEM FOUND THE PLUG ON THE COMPRESSOR WAS NOT MAKING A GOOD CONTACT REFITTED PLUG REMOVED THE GAS MEASURED 650 G OUT. REPLACED WITH 1100G AS PER SPEC TESTED OK CHECKED AIR CLEANER BEARING CULD DO WITH BEING REPLACED	VOLVO -
02/9/11	5287	<b>500 HRS SERVICE</b> – ENG OIL CHNAGED AND FINAL DRIVES. FILTERS ENG	MARK L - 31409

# Volvo EC460 CL Machine History

		AND FUEL. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED COOLANT OK. ANTIFREEZE – 21 BATTEREYS CHECKED CLENEED AND GREASED. MACHINE GREASED. LIGHTS OK SAMPLE ENG HYD ANF FINAL DRIVES	
01/9/11	5147	<b>VOLVO</b> – AC FAULT. INTERMITTANT AC FAULT INVESTIGATED SYSTEM FOUND THE PLUG ON THE COMPREEOR WAS NOT MAKING A GOOD CONTACT REFITTED PLUG REMOVED THE GAS MEASURED 650 G OUT REPLACED WITH 1100 G AS PER SPEC	VOLVO-
16/11/11	5608	<b>750 HRS SERVICE</b> - CHNAGED FUEL FILTERS. CHECK FINAL DRIVES. SLEW OK ENG TOPPED UP 2L HYD OIL OK. BALANCE WEIGHT LOOSE BOLTS SIZED. TOP UP BATTERY WITH WATER. BUCKET RAM FLEXI HOSE WEEPING	PAUL L- 31735
23/12/11	5771	REMOVE COUNTER WEIGHT DRIL OUT BROKEN BOLTS AND REFIT WELD ALL NEW BOLTS TOURQUE MAIN BOLTS TO 1900 NM. RESEAL WIRE HARNESS FROM ENGINE ROCKER COVER. REPAIR ALL LIGHTS. REPAIR HAND RAILS AROUND TOP OF MACHINE 2 X FRON SCREENS REPLACED	STEVE M - 32654
21/12/11	5770	RH SLEW MOTOR FRONT SEAL REPLACED. GREASE PIPES TO QUICK HITCH REPAIRED AND CLIPS MADE GOOD PIPES CLIPPED UP. ONE HYD HOSE TO SLEW MOTOR RESWAGED REAR WEIGHT REMOVED AND BROKEN STUD REMOVED. VARIOUS WORK LIGHTS REPAIRED AND WIRING MADE GOOD. RADIO HOUSING REPAIRED AND REFUSED. ALL ACCESS STEPS ON TRACK FRAME REMOVED BROKEN STUDS REPLACED AND STEPS STRIGHTENED. ANTIFREEZE CHECKED	PAUL H - 31221
09/1/12	5772	<b>1000 HRS SERVICE</b> – ENG OIL CHNAGED. SLEW AND FINAL DRIVES. FILTERS CHNAGED ENG FUEL HYD AIR CAB AND BREATHERS. OIL LEVELS OK. COOLANT OK. ANTIFREEZE – 32. BATTERY CHECKED. SLEW RING GREASE AND GREASE POT TOPPED UP. LIGHTS OK. SMAPLES ENG HYD SLEW FINAL DRIVES. 8 X BOLTS FITTED ON UNDER BELLY PLATES. NEEDS NEW LOCK FOR SMALL DOOR FOR ISOLATOR SWITCH	MARK L - 32515
10/1/12	5772	FIT 2 NEW HYD PIPES FROM VALVE BLOCK TO BASE OF BOOM FRO BUCKET RAM. FIT 2 NEW FINAL DRIVE DRAIN PLUGS. FIT NEW LOCK ON SIDE DOOR	STEVE M - 32658
29/02/12	6056	<b>250 HRS SERVICE</b> – FUEL FILTERS CHNAGED. OIL LVELS CHECKED SLEW MOTORS TOPPED UP AND HYD. COOLANT OK. ANTIFREEZE – 32 GREASE POT TOPPED UP. MACHINE GREASED SLEW RING LIGHTS OK	MARK L - 32299
01/05/12	6344	<b>500 HRS SERVICE</b> – ENG OIL CHNAGED. FILTERS CHNAGED ENG AND FUEL. AIR FILTERS BLOWN OUT. OILLEVELS CHECKED HYD TOPPED UP. COOLANT TOPPEDUP.BATTERY CHECKED. MACHINE GREASED. LIGHTS OK. SAMPLE ENG AND HYD	MARK L - 33285
15/05/12	6437	NEW PIN FITTED BUCKET END OF BOOM	MARK L - 3298
11/06/12	6612	REPAIR TIGHTEN BOLTS ON HAND RAIL LEKING HYD PIPE. ON BOOM.	PAUL L - 33248
26/06/12	6722	<b>750 HRS SERVICE</b> - CHNAGED FUEL FILTERS. CLEAN AIR FILTER.	PAUL - 36618
09/07/12	6773	REPLACED GREEN FLASHING BEACON SEAT BELT LIGHT	PAUL - 33634
01/08/12	6936	REPLACED HYD PIPE ON DIPPER RAM. NEEDS ASAP STRAIGHTEN STEEL HYD PIPE ON DIPPER RAM.,	PAUL - 34257
09/08/12	6981	REPLACED FUEL TRACK BOLTS. NEEDS 32 ONE SIDE 28 THAT OTHER SIDE.	PAUL - 34265
15/08/12	7011	CLEAN RAD WITH AIE GUN COMPRESSOR. BUCKET NO 560 CRACKS IN EARS AROUND BOSSES	PAUL L- 34275
31/08/12	7095	<b>1000 HRS SERVICE</b> – ENG OIL CHNAGED SLEW AND FINAL DRIVES. FILTERS CHNAGED ENG FUEL HYD AIR CAB AND BREATHER. OIL LEVELS CHECKED HYD TOPPED UP. COOLANT TOPPED UP. BATTEREYS OK. MACHINE GREASED. LIGHTS OK NEW RELAY FITTED. SAMPLE ENG HYD SLEW AND FINAL DRIVE	MARK - 34198
31/08/12	7095	FIT 12 TRACKS BOLTS	PAUL L- 34290
26/11/12	7445	<b>250 HRS SERVICE</b> - CHNAGED FUEL FILTERS. ENG OIL SLEW BOX ALL OK. LEFT AND RIGHT TRANS HUBS OK	PAUL - 34792
09/11/12	6405	<b>VOLVO</b> - SHOWING ERROR CODE MA2301-7. FAULTY INJECTOR REPLACVED INJECTOR.	VOLVO =
07/02/13	7755	<b>500 HRS SERVICE</b> - ENG OIL CHNAGED FILTERS CHNAGED ENG AND FUEL.	MAR KL= 35624

# Volvo EC460 CL Machine History

		AIR FILTERS BLOWN OUT. LEVELS OK COOLANT TOPPED UP ANTIFEEAZE – 32 BATTEREYS OK. MACHINE GREASED. LIGHTS OK SAMPLE ENG AND HYD	
15/02/13	7802	REPLACED 60 TRACK BOLTS RETIGHTEN THE REST	PAUL - 35338
16/04/13	8130	<b>750 HRS SERVICE</b> - CHANGED FUEL FILTERS	PAUL L- 35939
10/06/13	8422	<b>1000 HRS SERVICE</b> - ENG OIL CHNAGED SLEW FINAL DRIVE. FILTERS ENG FUEL HYD AIR CAB AND BREATHERS. LEVELS OK COOLAT OK -32 BATTERY OK MACHINE GREASED LIGHTS OK SAMPLE ENG HYD SLEW AND FINAL DRIVE	MAR KL- 36320
01/08/13	8635	REPLACED GREEN SEAT BELT LIGHT. REPLACED GREASE PIPE ON BOOM	PAUL - 36393
09/08/13	8683	<b>500 HRS SERVICE</b> - ENG OIL CHNAGED. FILTERS ENG FUEL. AIR FILTERS BLOWN OUT. LEVELS OK 2 X SLEW TOPPED UP. COOLANT OK -32 BATTEREYS OK MACHINE GREASED. LIGHTS OK SAMPLE ENG HYD. MIRROR BY BATTERY BOX MISSING	MARK L- 37357
28/08/13	8795	REPAIR GREASE PIPE ON QUICK RELEASE	PAUL- 37316
05/10/13	8975	<b>750 HRS SERVICE</b> - FUEL FILTERS CHNAGED. AIR FILTRS BLOWN OUT. LEVELS OK ENG TOPPED UP. COOLANT TOPPED UP. -32 BATTEREYS OK. MACHINE GREASED. LIGHTS OK	MARK L- 37651
04/11/13	9181	WELD SPLIT IN STEEL HYD PIPE ON BUCKET TILT RAM	PAUL- 37775
15/11/13	9266	GEITH QUICK HITCH RAM LEAKING. ON NOT DAMAGED	PAUL- 37794
25/11/13	9327	<b>1000 HRS SERVICE</b> - ENG OIL CHNAGED SLEW FD. FILTERS ENG FUEL HYD AIR CAB BREATHERS. LEVELS OK HYD TOPPED UP -46. BATTEREYS OK. NEW BATTERY FITTED BY STEVE L. MACHINE GREASED AND GREASE POT TOPPED UP. LIGHTS OK SAMPLE ENG HYD SLEW FD	MARK L- 38746
25/11/13	9826	REMOVE FAULTY BATTERYTS STRAIGHTEN BATTERY BOX FIT NEW BATTERY	STEVE L- 38518
28/11/13	9352	WELD STEEL HYD PIPE. NEEWS NEW	PAUL- 38556
05/12/13		CHECK REPAIR AND BUCKET RAM STEEL PIPE OK	STEVE L- 38535
16/12/13	9465	REPLACED HYD HOSE STEEL PIPE.	PAUL- 38565
10/12/13	3822	CENTRAL PIVOT ARM WELD REPAIR BRACKET. RETIGHTEN 3/8 HOSE ON VALVE BLOCK	PAUL- 38560
10/12/13	9431	REPAIR GREAE PIPE ON BOOM	PAUL - 38561
27/01/14	9668	<b>250 HRS SERVICE</b> - FUEL FILTERS CHNAGED. AIR FILTERS BLOWN OUT. LEVELS OK ENG AND HYD TOPPED UP. COOLANT OK -46 BATTEREYS OK. MACHINE GREASED. GREASE POT TOPPED UP. LIGHTS OK NEW BULB IN AMBER BEACON FITTED	MAR KL- 39106
06/03/14	9962	<b>500 HRS SERVICE</b> - ENG OIL CHNAGED. FILTERS ENG FUEL. AIR FILTERS BLOWN OUT. LVELS OK .COOLANT TOPPED UP – 32 BATTEREYS OK. MACHINE GREASED. LIGHTS OK NEW BULB FITTED AMBER BEACON SAMPLE ENG HYD. ENG OIL DRAIN VALVE NOT SEALING NEEDS NEW ONE RIGHT SIDE MIRROR CRACKED	MAR KL- 39873
24/03/14		REMOVE BUCKET RAM AND REMOVE AND CLEAN HYD HOSE ETC. REMOVE COOLER	STEVE L- 39592
04/04/14		FIT BUCKET RAM FIT BATTEREYS AND CLAMPS ETC	STEVE L- 39509
27/03/14		WELDING WORK. TO CHASIS SECTIONS. STARIGHTEN FRONT PANEL ON NS FRONT BELOW WINDOW AND REWELD. CUT OUT FRONT PANEL ON OF FRONT AND REPLACED. CUT OUT FRONT SECTION OF FLOOR IN BATTERY COMPARTMENT AND WELD BACK IN. WHERE BATTEREYS LIE FLATTEN FLOOR AND LINE WITH 6MM PLATE. REINFORCE UNDER FLOOR WITH 30 30 X3 RSA	VINCE - 39076
08/04/14		TIGHTEN TRACK PADS BOLTS NEW BOLTS	STEVE L- 39513
17/04/14		REMOVE QUICK HITCH -	STEVE L- 39527
22/04/14	10085	CHECK MC FIT BREAKER RETURN TO SITE REMOVE BREAKER HOSE. FIT NEW HOSE TOP UP OIL	STEVE L- 39528
12/04/14	110078	REMOVE ALL LOSSE TRACK PADS. CLEAN UP PADS AND CHAISN REFIT WITH	JAMIE- 38265

# Volvo EC460 CL Machine History

		NEW NUTS AND BOLTS. TOUQUE UP USING MULTIPLIER	
08/05/14		STRAIGHTEN OF TWO STEPS AND WELDING OF ONE.	VINCE - 39088
30/05/14	10252	<b>750 HRS SERVICE</b> - FUEL FILTERS CHNAGED. AIR FILTERS BLOWN OUT. LEVELS OK ENG AND HYD TOPPED UP. COOLANT TOPPED UP – 32 BATTEREYS OK. MACHINE GREASED LIGHTS OK AMBER BEACON MISING. RIGHT HAND SIDE TRACK PUMPED UP	MARK L- 39197
31/05/14	10253	ASSIST WITH FITTING OF GRAB ZX350 CUT OF WEAR BARS FROM BOOM WHERE GRAB TO BE WELDED TO BOOM GRIND FLAT FOR WELDING	BRIAN - 39802
03/06/14	10258	STEAM CLEAN MC AND USING WIRE WOOL	BRIAN - 39804
25/06/14	10270	SLEW AULT CHNAGED VLAVES AND CHECK PRESSURES AND AC. SYSTEM WITH VOLVOV FITTER PRESSURE VALVE CHNAGED VOLVO	STEVEL- 40500
26/06/14	10271	REPLACED EXPANSION VALVE ON AC. DEGAS AND REGAS SYSTEM OK	WILL- 40552
17/08/14	10347	REPLACE STEPS. REPLACE GREASE POT. HYD LEAK RECTIFIED.	DAVE K - 10347
08/09/14	10387	REPAIR TIN WORK. REMOUNT GREASER UNIT. REMOUNT BATTERY BOX. FIT CAMERA KIT. REPLACE BEACON. REFIT MIRROR. REPAIR OIL LEAK. REPAIR QUICK HITCH.	MITCH - 39221
04/10/14	10457	REMOVE 2 × BOOM RAMS AND DIPPER RAM AND HAVE RESEALED BY BLACK GOD HYDRAULICS. REFIT RAMS TO MACHINE. DRILL OUT BROKEN BOLTS ON DIPPER RAM CLAMP. FIT NEW O RINGS TO SLEW MOTOR CHECK VALVES. ALL LIGHTS CHECKED. FITTED NEW EXHAUST PIPE FROM TURBO.	STEVE M - 38423
17/10/14	10530	<b>1000 HRS SERVICE</b> – OIL CHANGED – ENG, SLEW × 2 AND FINAL DRIVE × 2. FILTERS CHANGED – ENG, FUEL, HYDS, AIR, CAB AND BREATHERS. OIL LEVELS CHECKED – ANTI FREEZE READING =-32DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED. SAMPLES TAKEN – ENG, HYD, SLEW ×2 AND FINAL DRIVE ×2.	MARK L - 41375
11/11/14	10672	CHECK FOR BOOM WIRE LIGHT. RUN FEED TO LIGHTS. ENGINEER REQUEST: SWITCH REQ.	PAUL H - 41498
10/12/14	10789	REPLACE PIPE ON HAMMER/LENGTH BY 1 FOOT. REPLACE PIPE ON BUCKET CONROL ON BOOM.	MARK H – 41426 B
24/11/14	10729	REPLACE HYD PIPE ON SERVO PIPE.	MARK H – 41421
19/12/14	10836	<b>250 HRS SERVICE</b> – FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG AND LEFT SLEW TOPPED UP. COOLANT TOPPED UP – ANTIFREEZE READING =-21DEG. BATTERIES CHECKED. GREASED POT FILLED. LIGHTS CHECKED.	MARK L – 41909
03/02/15	10955	CHECK FOR COOLANT LEAK. REMOVE PANEL UNDER CAB AND REPLACE HOSE CLIP ON HEATER HOSE. TOP UP COOLANT. REPLACE BROKEN BOLTS ON TRACK STEPS.	P HARTLEY – 42045
11/01/15	10863	REPLACE BUCKET TEETH.	MARK H – 41433
	10994	TIGHTEN HAMMER BOLTS.	P HARTLEY – 42607
06/03/15	11060	<b>500 HR SERVICE</b> - ENG OIL CHNAGED. FILTERS ENG & FUEL. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT CHECKED -ANTI FREEZE READING = – 32 DEG. BATTERIES CHECKED. MACHINE GREASED & GREASE POT TOPPED UP. LIGHTS CHECKED. SAMPLES TAKEN – ENG & HYD.	MARK LINES – 42691
02/03/15	11046	WELD BOXING RING POSTS.	S LLOYD - 1130
02/06/15	?	SNAPPED UPRIGHT ON BOX RING RAIL – WELD IN POSITION. ENG COMMENTS: NEW UPRIGHT REQ – PRONE FOR BREAKING @ WELD.	RUSSELL BUSH – 44359
11/06/15	11174	FIT LINE EXTING TO CAB. FIT STEP TO TRACK FRAME. REPLACE BUCKET PIN BOLT – CHECK QUICK HITCH. CHECK FOR CAMERA FAULT.	P HARTLEY – 43929
19/06/15	2579?	REPLACE BROKEN TILT RAM HOSE ON DIPPER ARM (BUCKET).	RUSSELL BUSH - 44377
11/07/15	11290	<b>REMOVE BOTH WORN TRACK CHAINS WITH 700 MM PAD. REPLACED 2 LOWER ROLLERS (1 EACH SIDE). HAVE ALL 4 TRACK GUIDS REPAIRED &amp; BUILT UP.</b>	SIMON / S MARSH 38438.

# Volvo EC460 CL Machine History

		<p><b>FIT NEW SPROCKETS.</b>  <b>FIT NEW TRACK CHAINS WITH 600 MM PADS.</b>  REPLACE 2 X HYDRAULIC HOSE FROM SPOOL TO BACK OF BOOM FOR DIPPER CURCIT.  REMOVE BELLY PLATES AND STRAIGHTEN.  REPLACE 1 HYDRAULIC HOSE FROM BOOM TO DIPPER FOR HAMMER CIRCUIT.  CHECK AND REPAIR ALL LIGHTS.  REPLACE CRACKED LOWER FRONT HITCH PLATE SCREEN.</p>	
26/06/15	1124	REPLACE DIPPER RAM PIPE ON DIPPER (FLEXY). REPAIRS TO RAIL ON REAR CONTER WAGRET. REPLACE O RINGS ON SLWE MOTOR PIPES. FIT NEW WIPER ON FRONT SCREEN.	M HILLMAN – 43428
28/07/15	1130	<b>750 HR SERVICE:</b> FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED.	MARK LINES – 44657
28/08/15	11498	MAKE UP GREASE PIPE FOR DIPPER ARM. TIGHTEN TRACK. TIGHTEN SPROCKET BOLTS ON LEFT. REPAIR WIRING & REPLACE GREEN LIGHT.	P HARTLEY – 46358
08/09/15	11535	REPLACE HYD PIPE ON BOOM RAM.	M HILLMAN – 44459
15/10/15	11710	WELD CRACKS IN BUCKET. WELD & PLATE GRAB HANDLE ON TOP OF BATTERT BOX. REPLACE O RING ON DIPPER RAM FITTING. REMOVE CAT WALK & REPAIR HYD OIL LEAK ON VALVE BLOCK. REMOVE REAR DOOR STRAIGHTEN & WELD DOOR HINGE. REPAIR WIRING TO GREEN LIGHT.	P HARTLEY – 46748
15/10/15	11710	<b>1000 HR SERVICE:</b> OIL CHANGED – ENG, SLEW X 2, AND FINAL DRIVE X 2. FILTERS CHANGED – ENG, FUEL, HYD’S, AIR, CAB, & BREATHERS. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED. SAMPLES TAKEN – ENG, HYD, SLEW X 2, AND FINAL DRIVE X 2. <b>ENG COMMENTS:</b> ENGINE COVER DOOR BOTTOM HNDGE U/S – FUEL FILTER SIDE.	MARK LINES – 47382
09/11/15	11797	FIT MESH TO ROCK GUARD. REPAIR WIRING TO CAMERA (BEHIND SEAT). REPLACE HYD PIPE ON PUMP TO ACCUMULATOR.	P HARTLEY – 46832.
05/11/15	11791	REPLACE MAIN OIL FEED TO PUMPS. FROM TANK PIPE. RE-FILL OIL & TOP UP & RUN ETC.	M HILLMAN – 44485.
10/11/15	11798	INVESTIGATE LEAKING OIL PIPE O RING. TIGHTEN RUN & TEST.	R MERRYDEW – 46960.
19/11/15	3174	DIPPER ARM RE-ATTACHED TO MACHINE. NUMEROUS HYDRAULIC LEAKS. (PIPES, FITTINGS, O RINGS). THOURGH CLEAN. GENERAL INSPECTION LIGHTS & LEVELS. SPROCKET BOLTS LOSE, NEW FITTED – (TORQUED APPROPRTATLEY).	D SHOWERING M HILLMAN – 43614.

# Volvo EC460 CL Machine History

		QUICK HITCH REPAIRED, NEW MECHANISM FITTED.	
23/11/15	?	<b>REPLACED FLANGE SEAL.</b>	HYDRAQUIP – 1105.
14/12/15	11896	<b>REPAIR 2 X GREASE PIPES ON DIPPER ARM.</b>	P HARTLEY – 45041.
08/01/16	11958	<b>REPLACE HYD ‘T’ ON SWNG MOTOR. FIT NEW STAND &amp; PIPE O RINGS ETC. REPLACE BOLT IN BUCKET BOSS FOR PIN RETAINER.</b>	M HILLMAN – 45359.
19/01/16	11993	REPLACE SERVO PIPE ON SPOOL BLOCK. REFILL OIL (HYD). RUN & CHECK ETC.	M HILLMAN – 45361.
01/02/16	12039	REPLACE TRACK MOTOR PINS. WELD & REPAIR BOXING RING.	P HARTLEY – 45266.
02/03/16	12107	REPLACE 3 X HAMMER BOLTS. REPLACE BEACON BULB. TIGHTEN 6 X HAMMER BOLTS. REPLACE CAB WORK LAMP & REPAIR BRACKET. TIGHTEN BOXING RING SUPPORTS. CARRY OUT INSPECTION: STEAM CLEAN MACHINE. <b>ENG COMMENTS: ALT DRIVE BELT REQ. FAN BELT REQ.</b>	P HARTLEY – 45969.
22/03/16	12174	REMOVE BROKEN SPRING FROM QUICK HITCH. PUMP UP TRACKS. CHECK LIGHTS & LEVELS. <b>ENG COMMENTS: 1 BUCKET OF GREASE FOR AUTO GREASERS.</b>	R MERRYDEW – 46126.
23/03/16	12185	<b>FIT 2 NEW SPRINGS ON QUICK HITCH.</b>	R MERRYDEW – 46128.
30/03/16	12210	WELD UP BROKEN POINTS ON SAFTY RING & WELD UP BROKEN HAND RAIL.	R MERRYDEW – 46132.
05/04/16	12251	<b>WELD UP BROKEN HAND RAIL. DRILL OUT BROKEN BOLT ON STEP. THEN REPLACE WITH NEW ONE.</b>	R MERRYDEW – 46145.
11/04/16	12263	<b>250 HRS SERVICE –</b> ENGINE OIL CHANGED. FILTERS CHANGED. – ENGINE AND FUEL. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTIFREEZE READING = -32DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. SAMPLES TAKEN-ENGINE AND HYDRAULIC. <b>ENG COMMENTS:</b> BOXING RING NEEDS WELDING, HEATER BLOWER NOT ALWAYS BLOWING, LEAK ON DIPPER RAM. CAP FOR HAMMER PIPE CONNECTION MISSING – MARK HILLAMN ON WAY TO REPAIR.	M. LINES – 47698
25/04/16	12313	STRAIGHTEN TRUCK STEPS. CRACK IN MAIN BOOM REPORTED. <b>ENG COMMENTS: (FAN BELT REQ A S A P)</b>	P HARTLEY – 48062.
26/04/16	12313	REPLACE FAN & ALT BELTS.	P HARTLEY – 48063.
19/05/16	12412	<b>500 HRS SERVICE</b> ENGINE OIL CHANGED FILTERS CHANGED – ENG & FUEL. AIR FILTERS BLOWN OUT OIL LEVELS CHECKED – HYD TOPPED UP COOLANT TOPPED UP – ANTI FREEZE READING = - 32 DEG BATTERIES CHECKED MACHINE GREASED LIGHTS CHECKED SAMPLES TAKEN – ENG HYD <b>ENG COMMENTS: OIL LEAK FROM DIPPER RAM</b>	M. LINES - 48186

# Volvo EC460 CL Machine History

11/07/16	12492	HYD PIPE O/S BOOM LEAKING FROM FITTING (BUCKET RAM) 1 X 5GAL ZS46 ADDED	T. VAILES – 48980
19/07/16	12518	SUPPLY 2 X FEMALE BLANK BUNGS 1” 1/34 FOR HAMMER PIPES A BEEN LOST BY DRIVER.	T VAILES - 48987
03/08/16	12530	REPLACED HEATER HOSES FROM ENG BAY TO CAB. REPLACED O RINGS IN ALL SPOUL END CUPS (X20). PUT WHITE TRAVEL LIGHT TO REAR OF MACHINE. <b>ENG COMMENTS:</b> DIPPER DROPS. PROBLEM IN SPOUL BLOCK.	L MULLINS – 47920.
08/08/16	12533	TO FIT HAMMER TO MACHIEN & TEST = OK. CUT & FIT A MESH TO FRONT WINDOW.	S HARVEY – 49149.
01/09/16	12629	<b>750 HR SERVICE:</b> FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG & HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED.	MARK LINES – 49728.
14/09/16	12841	<b>1000 HR SERVICE:</b> OIL CHANGED – ENG, SLEW, AND FINAL DRIVE X 2. FILTERS CHANGED – ENG, FUEL, HYD’S, AIR, CAB, & BREATHERS. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED. SAMPLES TAKEN – ENG, HYD, SLEW X 2, AND FINAL DRIVE X 2.	MARK LINES – 49809.
12/09/16	12632	<b>HAMMER NOT WORKING / SLOW.</b> VALVE TAPS ON DIPPER SENSOR SEMI CLOSED DUE TO LOCKING BALL / SPRING MISSING.	T VAILES – 50111.
18/08/16	12584	CHANGE SWIVEL JOINT SEALS ON ATLAS COPCO HB4200.	R BUSH – 48872.
06/10/16	1270	DIPPER REMOVED FOR WELDING FROM MACHINE. DIPPER ARM RE-ASSEMBLED TO MACHINE. QUICK HITCH REMOVED FROM MACHINE. SPOOL BLOCK WASHED OFF AND CHECKED FIR LEAKS – O RING CHANGED. M HILLMAN CHANGED O RINGS DAY BEFORE WHERE LEAKING. LIGHTS ARROUND MACHINE GAURDED WITH FINGER MESH. HAMMER PIPES FITTED. HAND RAIL WELDED WHERE CRACKED. BELT PULY CHANGED X 2. BELT TENSIONER PULLYS CHANGED X 2.	D SHOWERING & M HILLMAN – 48330.
10/10/16	12701	REPLACED HAMMER RETURN FILTERS.	J WYATT – 49865.
28/06/16	12737	TO TIGHTEN LOOSE L/H HAMMER FEED HOSE & TOP UP OIL 40L 46S. WELDED BACK ON L/H.	SIMON HARVEY – 50670.
01/11/16	12756	TO TIGHTEN LOOSE HAMMER PIPE. FIT MISSING HAMMER TOP HANDLE & SECURE WITH 2 JUBILEE CLIPS, CHECK OTHER PIPES FOR TIGHTNESS. TOP UP HYDRAULIC OIL 25L 46S.	S HARVEY – 50711.
03/11/16	12766	FIT HYD PIPE TO VALVE CHEST. INVESTIGATE HEATER FAULT – JUST BLOWS COLD – STRIP DOWN. FAN COWLING AND FIUND HEATER CONTROL PUSH ROD HAS DETACHED FROM HEAT CONTROLL VALVE – CLIP BACK ON – TEST – OK.	R BUSH – 50316.
08/11/16	12793	REPLACE LEAKING HYD HOSE @ QUICK HITCH.	RUSS BUSH – 50320.
09/11/16	12820	JOURNEY TO G3 SUMP INSPECT HAMMER FOR LEAK. TIGHTENED LOOSE SUPPLY HOSE ON HAMMER & TOPPED UP OIL. 20L 46S. CHECKED ENGINE OIL	S HARVEY – 50724.



# Volvo EC460 CL Machine History

		& COOLANT OK.	
18/11/16	11572	TO REPLACE 2 BLOWN HYDRAULIC HOSES. TOP UP OIL 100L 46S & TEST = OK. LEVELS & LIGHTS ALSO OK. UNBLOCK FUEL TANK BREATHER. <b>ENG COMMENTS:</b> FITTED PIPE, RUSSELL REMOVED THEN BLEW ON START UP.	S HARVEY – 50735.
05/12/16	12938	TO REPLACE 2 HYDRAULIC HOSES ON SLUE MOTOR & TOP UP OIL. REPLACED R/H MIDDLE BOXING RING UPRIGHT. STRIPPED OUT PANELING BEHIND SEAT TO INSPECT HEATER UNIT. NEW HOT / COLD CONTROL REQUIRED.	SIMON HARVEY – 50694.
13/12/16	12963	STRIP OUT R/H CONSOLE & TIGHTEN LOOSE HYDRAULIC PIPE THAT FEEDS LEVER (JOYSTICK). LEVELS & LIGHTS CHECKED = OK.	S HARVEY – 50699.
16/01/17	13040	<b>250 HR SERVICE:</b> FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – ENG, HYD, & LEFT SLEW TOPPED UP. COOLANT TOPPED UP – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. <b>ENG COMMENTS:</b> DRIVERS SIDE MIRROR CRACKED. WINDSCREEN WASHERS NOT WORKING.	MARK LINES – 51791.
06/01/17	13000	<b>TO REMOVE BREAKER POINT &amp; INSPECT = OK.</b>	S HARVEY – 51511.
17/01/17	13034	POINT INSPECTION ON V55 BREAKER. SERIAL NO: V055450302]. ALL OK.	RUSSELL BUSH – 48846.
19/01/17	13047	<b>MIRROR FITTED:</b> CHECK OUT WINDOW WASHER FAULT – GOT POWER TO PUMPS BUT PUMPS FAULTY, NEW ORDERED.	RUSSELL BUSH – 50295.
16/12/16	?	<b>FIT HYDRAULIC HOSE @ MAIN HYD PUMP.</b>	RUSSELL BUSH – 50293.
13/02/17	13144	TO FIT A NEW HAMMER POINT & INSPECT HAMMER – OK. GRAVE HAMMER A GOOD LOOKING OVER & INSPECTION OK. VERY SLIGHT FILM AT BRASS ON ACTUALL HAMMER POINT BUT ALL BUSHES LOOK GOOD AND GETTING PLENTY OF LUBRICATION. <b>ENG COMMENTS:</b> SECOND POINT IN AS MANY MONTHS, OPERATOR ERROR	S HARVEY – 51676.
15/02/17	13150	TO REFIT PIPE CLAMP TO DIPPER WITH NEW BOLT CHECKED & TIGHTENED ALL THE REST. REPAIRED 2 BOOM RAM BEARING GREASE PIPE. LEVELES CHECKED TOPPED UP ENGINE OIL 5L 15/40. TIHTENED VARIOUS LOOSE PANEL BOLTS.	S HARVEY – 51674.
31/01/17	?	TO REPLACE CUTTING EDGE WITH NEW BOLTS & REPLACE FUSE FOR CAMERA & WEIGHER. LEVELS CHECKED – OK.	S HARVEY – 51661.
?	13224	TO REMOVE POINT FROM HAMMER FOR INSPECTION. FOUND BROKEN. GREASE SEAL & DAMAGE TO BRASS BUSH TO MEASURE & REPORT ON FINDINGS. (S MARSH INFORMED).	S HARVEY – 51617.
01/03/17	13214	<b>CHECK OUT HYDRAULIC LEAK. REPLACED LEAKING O RING ON MAIN PUMP. TOP UP OIL 20L 46 &amp; CHECKED LEVLES = OK.</b>	S HARVEY – 51614.
03/02/17	13100	ERROR CODES MT 2301-5; MA2302-5; MA2303-5. CHECK FOR ENGINE MISSFIRE REPLACED ENGINE MANAGEMENT LOOM. REPLACED INJECTOR NO: 2 SET TAPPETS INLET 0.2MM EXHAUST 03.MM. RUN UP TEST OK – CHECKED LEVELS – OK.	S HARVEY – 51604.
26/01/17	13092	FIT TWO WASHER PUMP MOTORS.	RUSS BUSH – 51567.
20/03/17	13258	<b>500 HR SERVICE:</b>	MARK LINES –

# Volvo EC460 CL Machine History

		ENGINE OIL CHANGED. FILTERS CHANGED – ENG & FUEL. AIR FILTERS BLOWN OUT. OIL LEVELS HECKED. COOLANT HECKED – ANTI FREEZE READING = -32 DEG. BATTERIES CHECKED. MACHINE GREASED. LIGHTS CHECKED. SAMPLES TAKEN – ENG & HYD.	52315.
11/03/17	13229	TO FIT A NEW GREAE WIPER SEAL & REFIT POINT AFTER KELLANDS INSPECTION (TOLD TO FIT NEW SEAL & CARRY ON USING).	S HARVEY – 51632.
28/03/17	13229	<b>HAMMER INSPECTION:</b> CRACK SPLIT IN RUBBER BETWEEN HAMMER AND HEAD.	T VAILES – 51728.
31/03/17	13322	HAMMER RETURN HYD PIPE REPLACED. CHECKED & TOPPED UP HYD LEVEL – OK.	T VAILES – 51731.
04/04/17	13335	<b>REPLACE MIRROR FRONT O/S.</b>	T VAILES – 51735.
12/04/17	13372	<b>AC REGAS:</b> REVOCERED – 43G RECHARGED – 1100G	T VAILES – 51744.
24/04/17	13411	<b>HAMMER TIP BROKE IN HALF:</b> OLD TIP REMOVED FROM HAMMER AND NEW FITTED. WELDED TRACK PIN – WORKING LOOSE. ORANGE BEACON BULB FITTED. GREASE PIPES ON H FRAME, DAMAGED AND BROKEN. PIPES AND FITTINGS REPAIRED.	D SHOWERING & T VAILES – 50942.
22/04/17	13392	TOP RAM ON BOOM TO DIPPER PIN PLATE BRAKEN – RE-WELDED. REPLACED 1 X BOXING RING POST.	T VAILES – 54156.
08/05/17	13485	<b>750 HR SERVICE:</b> FUEL FILTERS CHANGED. AIR FILTERS BLOWN OUT. OIL LEVELS CHECKED – HYD TOPPED UP. COOLANT CHECKED – NTI FREEZE READING = -21 DEG. BATTERIES CHECKED. GREASE POT TOPPED UP. LIGHTS CHECKED. <b>ENG COMMENTS:</b> BOTTOM HINGE ON AIR FILTER SIDE DOOR BROKE.	MARK & RICH – 54373.
25/05/17	13542	REPLACED GREEN LIGHT WORING. REPLACED GREASE POT PLUNGER VALVE.	J WYATT – 51185.
14/06/17	13621	<b>A/C NOT WORKING.</b> CONDENSOR SPLIT – NEW ORDERED. STOPPED REFILL & VAC OUT SYSTEM WHILSE WAIT FOR PART.	T VAILES – 54921.
15/06/17	13624	FIT HAMMER GREASE FEED PIPE.	R BUSH – 52775.
23/06/17	13640	REPLACED AIRCON CONDENSER (HAD A HOLE IN) WELDED HINGE ON ACCESS DORR TO A/C CONDENSER AS HAD SNAPPED OFF.	J WYATT & R BUSH - 52695
26/06/17	13640	REPLACE BROKEN MIRROR O/S/CAB	R BUSH - 52781
27/06/17	13642	REGAS A/C SYSTEM + TEST TEMP TP 4.7 C	T VAILES - 54929
29/06/17	13649	LEFT HYD FEED PIPE ON HAMMER CHECK OIL LEVEL - OK	T VAILES - 54939
05/07/17	13679	TOP UP HYD OIL 30LTRS ZS46	T VALIES - 54949
12/07/17	13716	FUEL FILTERS CHANGED – NEW WATER TRAP ORDERED ADJUST MESH ON SIDE WINDOW FIT RUBBER AROUND HAMMER PIPE – PREVENT RUBBING	T VAILES - 52859
20/07/17	13764	<b>1000HR SERVICE &amp; INSPECTION</b>	R.GAMBLIN -

# Volvo EC460 CL Machine History

		FUEL FILTER CHANGED OILS CHANGED – ENG/SLEW/2XFINAL DRIVES. FILTERS CHANGED – ENG/HYD/HP HYD/ CAB/ BREATHER AIR OIL LEVELS CHECKED BATTERIES CHECKED MACHINE GREASED LIGHTS CHECKED SAMPLES TAKEN. ENG/ HYD/SLEW/ FINAL DRIVES X2. <b>ENG COMMENT:</b> WASHER BOTTLE MOTOR BRAKE ON SITE FILTERS AWARE.	52967
24/07/17	13770	BELLY PLATE ALL SMASHED OFF – WELD LUGS BACK ON EXTRACK STUDS RE ATTACH BELLY PLATE.	R.BUSH - 52820
24/07/17	13770	REPLACE WATER FEED TRAP SENSOR	T.VAILES - 52874
20/07/17	???	WELDED THE PART OF THE QUICK HITCH THAT ATTCHES TO THE BUCKET BACK ON BECAUSE IT HAD SNAPPED OFF.	ADAM HAMILTON - 54463
10/08/17	13866	<b>CHANGE BROKEN POINT ON V5J BREAKER</b>	R.BUSH - 54219
12/09/17	14023	<b>250HR SERVICE</b> QUICK INSPECTION LIGHTS AND LEVELS HYDRAULIC OIL ADDED	D.SHOWERING - 53370
09/10/17	14086	MACHINE WILL NOT START – BLEED UP FUEL SYSTEM + BLOW OUT AIR FILTER STARTS OK TIGHTEN LOOSE FITTING AT CHECK VALVE ON DIPPER RAM	R.BUSH - 53580
29/09/17	14057	ASSISTED L MULLINS AND S PAINTING IN REFITTING DIPPER RAM ALL PIPE WORK RECONNECTED AND CLAMPS REATTACHED FITTED MASTER LINK LOCKING PIN WITH L MULLIN TOPPED UP HYDRAULIC OIL ZS46X 16 GALLONS	J.WYATT - 55077
08/11/17	14236	FITTED NEW ½ UNF X 2.5 BOLT TO RHS OF HAMMERS PIPE CLAMP (OLD BOLT MISSING)	J.WYATT - 55346
13/11/17	14247	FITTED NEW WASHER BOTTLE	J.WYATT - 55350
17/11/17	14285	REPLACED ALTERNATOR/ AIR – CON BELT - OLD BELT MISSING 50% CIRCUMFERENCE	J.WYATT - 55861
22/11/17	14299	<b>500HR SERVICE</b> CHANGED ENGINE (3) + FUEL FILTERS (2) SAMPLED ENGINE + HYD OIL CHANGED ENGINE OIL ALL LIGHTS AND LEVELS CHECKED BATTERIES – CHECKED COOLANT -46	A. RUNNACLES - 55780
15/01/18	14534	<b>750HR SERVICE</b> CHANGED FUEL FILTERS X 2 LIGHTS AND LEVELS CHECKED  BATTERIES - CHECKED COOLANT - 46	A RUNNACLES - 56371
02/01/18	14630	REMOVE + REPLACE MAIN HYD PIPE FROM PUMP TO SPOOL BLOCK TOPPED UP WITH OIL	T.VAILES - 56954
02/02/18	14638	REPLACE O-RING ON PIPE	T.VAILES - 56955
26/01/18	14566	REFIT SWING JOINT ON V55 BREAKER (HYD PIPE BOLTS SNAPPED)	R.BUSH - 55630
07/02/18	???	WELDED 3 CRACKS ON THE DIESEL TANK TESTED WELDS BY FILLING TANK WITH AIR AND PUTTING SOAPY WATER ON MY WELDS AND THERE WERE NO BUBBLES. PAINTED WELDED	A. HAMILTON - 56855
14/02/18	???	HYD LEAK ON DIPPER – LOOSE FITTING – TIGHTEN OK	R.BUSH - 56908

# Volvo EC460 CL Machine History

		CHECK HAMMER WAS GETTING GREASE	
14/02/18	14647	FIT HAMMER	R.BUSH - 56906
15/03/18	14715	REPLACE MISSING LIGHT SWITCH	R.BUSH - 56919
04/04/18	14797	<b>1000HR SERVICE + INSPECTION</b> OILS CHANGED + SAMPLED – ENG, FINALS, SWING X 2 SAMPLED – HYD  FILTERS CHANGED – ENG X3, FUEL X2, HYD X3, AIR X2, CAB X2, HYD BREATHER.  LIGHTS AND LEVELS CHECKED  BATTERIES – CHECKED COOLANT - 46	A RUNNACLES - 57483
22/03/18	14744	REPLACE BLOWN O RING ON TANK RETURN PIPE (HYD)	R.BUSH - 57519
01/05/18	14902	REPLACE DIPPER RAM HOSE.	M.PALMER - 59103
01/05/18	14873	FIT NO'2 BATTERY RELAY @ FUSE BOX	RUSSELL BUSH - 57554
02/05/18	14393	FIT HYD PIPE TO BREAKOR	RUSSELL BUSH - 57556
29/05/18	15042	<b>250HR SERVICE</b> ENG OIL CHANGED + SAMPLED HYD SAMPLED  FILTERS CHANGED – ENG X3, FUEL X2 LIGHTS + LEVELS CHECKED  BATTERIES – CHECKED COOLANT - 46	A RUNNACLES - 59262
01/06/18	15059	REMOVED THE 2 OIL PIPES TO THE FILTER HEAD TOOK OVER FROM MITCH REFITTING, CHANGED PILOT FILTER + HAND RAIL	A RUNNACLES - 59269
30/05/18	15049	CROSS OVER PIPES ON PILOT FILTER	M.PALMER - 59119
12/06/18	15101	WELD 6 BELLY PLATE LUGS ON & FIT BELLY PLATE	R BUSH - 56926
11/06/18	??????	WELD ON HANDRAIL TO BOXING RING STEPS TO ENG BACK REAPIR STEP ON TRACK FRAME	T VAILES - 56977
22/06/18	15174	WASH OUT HYD COOLER, RADIATOR + A/C COOLER CLEAN HAMMER VSS TO CHECK FOR OIL LEAK UNDER INVESTIGATION	T VAILES - 56986
13/07/18	15288	750HR SERVICE CHANGED FUEL FILTERS X2 LIGHTS AND LEVELS CHECKED  BATTERIES – CHECKED COOLANT - 46	A RUNNACLES - 59767
24/07/18	15329	WELD REPAIR TO BATTERY BOX LID. WELD REPAIR TO HAND RAIL @ STEPS WELD REPAIR TO BOXING RING UPRIGHT TIGHTEN FITTING ON MAIN SUCTION HOSE (HYD) FIT MIRROR	R BUSH - 59631
10/08/18	15366	REFIT HAMMER POINT LOCKING PIN	P.LINES - 59417
20/08/18	15402	REMOVE V55 BRAKER + FIT HIRED BREAKER TOP UP HYD OIL.	R BUSH - 58113
23/08/18	15406	REPLACE RETURN BOX ON HIRE HAMMER (FOX PLANT)	T VAILES - 56553

# Volvo EC460 CL Machine History

01/09/18	15444	NO POWER IN CAB BATTERIES OK ISOLATOR OK FUSES OK  REPLACED 4 PIN RELAY FOR BATTERY – CAB POWER	J WYATT - 58619
04/09/18	15454	PIN AT BASE OF DIPPER TO HAMMER HEAD - RETAINING BOLT MISSING - KNOCKED PIN BACK THROUGH & FITTED NEW BOLT  REPAIRED GREASE PIPE & FITTING ON END OF BUCKET RAM	J WYATT - 58625
10/09/18	15493	REPLACED HYD HOSE (TRACK MOTOR RHS – ROTARY CO-LING ) REPLACED O RING IN ADJACENT PIPE TOPPED UP HYD OIL ZS/40	J WYATT - 58637
19/09/18	15548	<b>1000HR SERVICE + INSPECTION</b>  OILS CHANGED + SAMPLED – ENG, FINALS, SLEWS + SAMPLED HYD  FILTERS CHANGED – ENG X3, FUEL X2, AIR X2, CAB X2, HYD X3, <b>HYD BREATHER</b>  <b>LIGHTS AND LEVELS CHECKED</b>  <b>BATTERIES – CHECKED</b> <b>COOLANT - 46</b>	A RUNNACLES - 58534
14/09/18	15520	REPLACED MIRROR ON SIDE OF CAB	J WYATT - 58647
27/09/18	15585	METAL HAMMER PIPES ON BOOM ARM – 2 HAD PINHOLES BY MATING FLANGES. REMOVED & WELDED. REFIT WITH NEW O RINGS. WELDED BROKEN PIPE CLAMP. TOPPED UP 2 GAL 25/46.	J WYATT – 58818.
01/10/18	15610	RADIO AND CAMERA U/S VOLTAGE DROPPED FEED HAS NO SUPPLY TOOK NEW FEED FROM SEATBELT SWITCH FITTED NEW HAMMER PPC	J WYATT - 58824
12/10/18	15676	HEADER TANK SPLIT REPLACED WITH NEW BOOM LIGHTS U/S FUSE BLOWS INSTANTLY REPAIRED PREVIOUS WIRING ON BACK OF BOOM ARM AND FITTED NEW H3 BULB TO TOP RHS LIGHT ON BOOM ARM	J WYATT - 58845
18/10/18	15690	OIL LEAK DROM HQAMMER FEED PIPE	T VAILES - 56583
22/10/18	15706	MONTEVERT VS5 SN V055H50302 REPLACED POINT (OLD POINT SNAPPED)	J WYATT - 58849
17/10/18	15691	FIT HAMMER TO MACHINE RE- BUILD HAMMER POINT, HEAD FIT HAMMER TAPS AND PIPES	M. PALMER - 58367
30/10/18	15730	TIGHTENED FITTING ON MONTEVERT V55 FOR HAMMER PIPE REPAIRED BROKEN LIVE FEED WIRE FOR CAMERA	J WYATT- 58669
13/11/18	15784	<b>250HR SERVICE</b> CHANGED FUEL FILTERS X2 LIGHTS+ LEVELS CHECKED	A RUNNACLES- 61331

# Volvo EC460 CL Machine History

		BATTERIES CHECKED COOLANT- 46	
14/11/18	15787	TIGHTENED HAMMER HEAD BOLTS NEW REQUIRED	J WYATT - 58695
22/11/18	15831	FITTED NEW ARMoured GREASE PIPE FOR LOWER H- LINK PIN	J WYATT- 61464
20/11/18	15813	FITTED 4X NEW HAMMER HEAD BOLTS ALL OTHERS STILL TIGHT REMOVED BROKEN GREASE PIPE- TO BE SENT TO YARD IN AFTERNOON TIGHTENED 4 BOLTS FOR HAMMER PIPE TO TAP AS LOOSE	J WYATT- 61461
23/11/18	15844	bled AIR OUT F AUTO LUBE SYSTEM REPAIRED SPILT GREASE PIPE RUNNING ALONG DIPPER ARM ALL JOINTS TAKING GREASE	J WYATT- 61471
7/12/18	15918	REPLACE POINT ON VSS HAMMER	MITCH/ JAMIE – 58400
11/1/19	16051	<b>500 HR SERVICE</b> <b>ENG OIL CHANGED AND SAMPLED HYD SAMPLED</b> <b>FILTERS CHANGED –ENGX3 , FUEL X2</b> <b>LIGHTS AND LEVELS CHECKED</b> <b>BATTERIESCHECKED</b> <b>COOLANT-46</b>	A RUNNACLES - 61842
31/1/19	16137	<b>REPLACED HYD HOSE FROM SPOIL BLOCK TO MAIN BOOM</b>	NICK PENNY- 58484
22/1/19	16073	<b>ADJUST WIPER ACTIuation TAB TOP LEFT OF CAB</b>	RUSSELL BUSH – 61450
21/2/19	16229	<b>HYD HOSE HALF CLAMP BLOTS LOOSE + O RING BROKEN</b> <b>FIT NEW O RING AND REFIT PIPE TIGHT</b> <b>TOPPED UP 15 GALLON 25/46 HYD OIL</b>	J WYATT- 60304
11/3/19	16300	<b>750 HOUR SERVICE</b> <b>CHANGED FUEL FILTERS X2</b> <b>LIGHTS AND LEVELS CHECKED, AIR/CAB FILTRERS CLEANED</b> <b>BRAKE TEST N/A</b> <b>BATTERIES CHECKED</b> <b>COOLANT -46</b>	ADAM RUNNACLES -
6/3/19	16282	<b>REPAIRED BROKEN GREASE PIPE ON BUCKET RAM</b> <b>REMOVED HANDAL FOR WELDING</b> <b>TOPPED UP HYD OIL 25/46</b> <b>REPLACED WASHER PUMP</b>	J WYATT- 60330
15/3/19	16323	<b>WELDED CHASIS UNDER DIESEl TANK</b> <b>REPLACED 4 HYD HOSE</b> <b>REFIT CENTER ROLLER (R/H) ADTER REMOVING 3 BROKEN BOLTS</b>	L MULLINS – T VAILES – M HILLMAN
1/4/19	16406	<b>,REMOVED 2X BOXING RING POLES</b> <b>STRAIGHTNED 1&amp; WELDED OTHER</b> <b>TAPPED MOUNTING HOLES &amp; REFIT WITH NEW BOLTS</b>	J WYATT- 60666
17/4/19	16436	<b>REFILL A/C</b>	K GEORGIEV- 61797
18/4/19	16430	<b>INSPECTED LIGHTS – ALL OK</b> <b>INSPECTED LEVELS ALL OK</b> <b>INSPECTED UNDERCARRIAGE ALL OK</b> <b>INSPECTED PINS/BUSHES/BEARINGS ALL OK</b>	J WYATT- 60676
23/4/19	16438	<b>REPLACE 2 O RINGS ON LOOSE HYD FITTINGS ON VALVE CHEST TIGHTEN</b> <b>4 HYD PIPE PUMP + VALVE CHEST</b>	RUSSELL BUSH – 60109
22/5/19	16591	<b>1000 SERVICE AND INSPECTION</b> <b>OILS CHANGED AND SAMPLED: ENGINE, SLEWS, FINAL DRIVES</b> <b>AND SAMPLED: HYDRAULIC</b> <b>FILTERS CHANGED: ENGINE X3 FUELX2 AIRX2 CABX2 HYDRAULIC X3</b>	ADAM RUNNACLES

# Volvo EC460 CL Machine History

		<b>HYDRAULIC BREATHER, HAMMER FILTERS X2</b> <b>LIGHTS AND LEVELS CHECKED</b> <b>BRAKE TEST: N/A</b> <b>BATTERIES CHECKED</b> <b>COOLANT-46</b>	
28/5/19	16613	<b>A/C NOT WORKING FOUND TO MUCH GAS IN SYSTEM</b> <b>RECOVERED 1658G OF GAS OML OIL</b> <b>RECHARGED AT 800G OF GAS OML OIL OML U.V</b> <b>TESTED SYSTEM ALL OK</b>	NICK PENNY - 60819
17/6/19	16711	<b>RESAMPLE RIGHT SLEW OIL (ADVICE FROM SAME REPORT)</b>	ADAM RUNNACLES
17/6/19	16715	<b>WELDED 1X BROEKN HANDRAIL</b> <b>WELDED 1X BOXING RING SUPPORT</b>	J WYATT- 63244
21/6/19	16716	<b>WELDED PIN – HOLE IN STEEL HAMMER PIPE ON BOOM ARM, REFIT WITH NEW BOLTS</b> <b>REPLACED O RINGS ON T—PIECE FITTING ON SPOOL BLOCK</b>	J WYATT – 63249
27/6/19	16742	<b>REMOVED MONTEBERT 55 HAMMER</b> <b>FIT ATLAS COPCO 250</b> <b>SHIMMED H- LINK &amp; DIPPER</b> <b>TESTED OK, RECCOMENDED TO NOT WE ABOVE THROTTLE SETTING G1 TO KEEP FLOW IN SUITABLE LEVEL</b>	J WYATT- 63661
28/6/19	16748	<b>FIT NEW PIPT CLAMP TO BUCKET PIPE ON END OF BOOM ARM</b>	J WYATT- 63668
10/7/19	16802	<b>REPAIRED WIRING FOR GREEN BEACON &amp; CAMERA FIT NEW 15 A FUSE</b>	J WYATT- 63684
08/07/19	16793	<b>REMOVED ATLAS COPCO HAMMER</b> <b>FIT MONTEBERT 55</b>	J WYATT - 63681
09/07/19	16794	<b>TOP UP HYD OIL '46' 60 LTRS</b> <b>REPAIR WIRING TO GREEN SEAT BELT LIGHT</b>	P. LINES - 63608
17/07/19	16862	<b>250 HOUR SERVICE</b> <b>CHANGED FUEL FILTERS X2</b> <b>LIGHTS AND LEVELS CHECKED, PROP SHAFTS GREASED, AIR/CAB FILTERS CLEANED</b> <b>BRAKE TEST: N/A</b> <b>BATTERIES CHECKED</b> <b>COOLANT: -46</b>	ADAM RUNNACLES
27/07/19	16915	<b>FIT NEW ALTERNATOR BELT</b> <b>RESEALED CAP ON SPOOL BLOCK</b> <b>TOPPED UP HYD OIL 25/46</b>	J. WYATT - 63865
13/1/19	16840	<b>40 LTRS 46 ADDED</b> <b>TIGHTON GREASE PIPE ON HAMMER</b> <b>TIGHTEN DRAIN BUNG ON TRACK MOTOR</b>	R. BUSH - 63455
29/07/19	???	<b>FIT HYD PIP &amp; DIPPER CHECK VALVE</b>	R. BUSH - 63464
01/08/19	16946	<b>TIGHTEN GREASE PIPE</b> <b>REWIRE STEREO</b> <b>ORDER SAFTEY RING UP RIGHTS</b> <b>INVESTIGATE OIL LEAK</b>	R. BUSH - 63466
07/08/19	16962	<b>FIT 2X NEW BOXING RING UPRIGHTS</b> <b>FIT CHAINS</b> <b>WELDED BROKEN HANDRAIL &amp; REAR LEFT BOXING RING UPRIGHT</b>	J WYATT - 63889
15/08/19	17014	<b>40 LTRS 25 46 ADDED</b> <b>CRIMP UP CONNECTORS ON DIN MOUNTED ORANGE BEACON</b>	R. BUSH - 63480
17/08/19	17025	<b>WELD PIN HOLE IN HYD PIPE (ATTACHMENT) ON BOOM</b>	R. BUSH - 63486
27/08/19	17080	<b>500 HOUR SERVICE</b> <b>ENGINE OIL CHANGED AND SAMPLED</b> <b>HYDRAULIC OIL SAMPLED</b> <b>FILTERS CHANGED: ENGINE X3, FUEL X2</b>	ADAM RUNNACLES

